


Tamiya LF Battery Notice

Dear Highly Valued Customer,


Thank you for purchasing our products and the continued support you have shown Tamiya over the years.

It has come to our attention that the exchange connector, which is included with a number of our LF Battery items, has been incorrectly assembled (see diagram below). We would like to ask you to refrain from using this connector as it may cause your Electronic Speed Controller (ESC) to explode or catch on fire. Please contact Tamiya Customer Service or your local Tamiya dealer for further assistance.

(Poor)



(Good)



Applied Products

Item 55102 Tamiya LF Battery LF2200-6.6V Racing Pack

Item 55104 Tamiya LF Battery LF2200-6.6V Racing Pack & LF-6.6V Battery DC Charger Set

Item 55105 Tamiya LF Battery LF1100-6.6V Racing Pack (M-Size)

Tamiya would like to sincerely apologize to our highly respected customers for any inconvenience this may have caused. From this, we will further improve our quality control systems so as not to allow this to happen again and we would like to thank you for your continued support.